

## T-Series IPPBX v4.0.3 Changelog

### Fixed/Optimized

1. Adjusted the default wake-up service voice prompt to play the system waiting music by default.
2. Removed the display of digital trunks and module settings menu from T100 and T200's trunk status.
3. Fixed the issue with the system's default ringtone time setting not working.
4. Fixed the issue where the device's virtual IP address cannot be cleared after turning off hot standby.
5. Fixed the issue where the device could not automatically restart after an upgrade is timeout (adjusted the maximum upload upgrade firmware timeout to 900 seconds).
6. Fixed the issue with the OpenVPN client certificate generation failure.
7. Fixed the issue where no certificate was displayed after uploading the OpenVPN client certificate.
8. Fixed the issue where analog trunk recordings could not be written to the database.
9. Fixed the issue where the GSM module had no sound and no incoming call display.
10. Fixed the issue where the invite teluri could not be recognized, causing call failure.
11. Fixed the issue where the phone could not download the configuration file automatically.
12. Fixed the issue with interface data display while capturing data packets of analog channel and network channel.
13. Fixed the issue where the vsftpd server could not be logged in.
14. Fixed the issue where looping coverage of recording files was ineffective.
15. Fixed the issue of backup recording files could not be looped over when the USB space is full.
16. Fixed the issue where changing the web access port failed.
17. Fixed the issue where the GSM trunk status displayed incorrectly.
18. Fixed the issue where SMTP email sending failed.
19. Fixed the issue where the static route might be lost after restarting the system.
20. Fixed the issue where the automatic backup settings were ineffective.
21. Fixed the issue where the FTP backup connection status couldn't refresh.
22. Fixed the issue where the static queue member sorting was reversed.
23. Fixed the issue where the FXO channel might produce noise.
24. Fixed the issue with T100's system storage display error.
25. Fixed the issue where numbers on the whitelist for outgoing calls was not effective.
26. Fixed the issue with some improper label descriptions.
27. Fixed the issue where the phone could not reach out and download the configuration file automatically via TFTP.
28. Modified the FXO and FXS module channel light color exception issue.

## Added

1. Added a ON/OFF switch for extension configuration of Softphone App registration and adjusted the registration account type (compatible with CooCall v302 and above).
2. Added all update version information to upgrade log history.
3. Added a refresh button for extension status.
4. Added the SIP trunk configuration function to the Quick Setup Wizard.
5. Added the function to modify the administrator username.
6. Added the function to force a data verification code after web login error more than three times.